	TAY TAY	10,	LIBER	1 PAGE 339	007226	5	
	1994 Alpena Mounty	Remonumentation Corner LAND CORNER F	r DDER	T WENNY	RI ALPEN	ECORDED A COUNTY MI	_
	EMONO.	LAND CORNER F	RECORDATION C	ERTIFICATE		000H[] [H]	L.
For	Corners in APR 0 6 1991	SION Filing Requireme	ent of Act 74, Mic		0Ec 12	9 31 AM 194	
1	11 pena COUNTY COMMING	Located in:	Corner Code ##		maria	o O. Johnston	
1 1	Public Land Survey	T 29N 8E	C-7		REGIST	ER OF DEEDS	
1	dulic cand Guivey	T R		-	,,mai41	en of Deeds	
		T R T R		- [
1	Property Controlling	S T R					
	n Section Miscellaneous	S T R S T R		Posiete	of Doods Sta	ma A File Nomb	
. 1	Property in Sec.	S T R		ueAiste		mp & File Numb	er
4. 1	ot No, Reco	orded Plat			A B C D E	FGHIJI	, I
5. Í	Private Claims	<u> </u>				FGHIJI	
	÷.	•		3	I I I		H
E	Carl T. Lewis	July 22 a field survey on	. 19	94 4	╼┆─┼┋┼	9	-
	ereby certify that under require	ements of P.A. 74, Michigan P.A. of 19 nformance with regulations and rul	70, the corner points	mentioned 6	-1817	16-1-15-1-14-	
curre	nt manual of survey instruction	ons of the United States Departmen	t of the Interior, Bure	au of Land 7	++-		\vdash
abov	e were in conformance with th	ourt of Law and/or that the corner poi te rules of the Michigan Board of Lar	nd Surveyors or by a [Decree of a	19 20	21-22-23-	24
	t of Law; established, fe-es essed below:	stablished, monumented, re-monu	mented, recovered,	found as	30 29	28-27-26-	<u></u>
тои	E: Not more than 4 corn on this certificate.	ers, all in the same town and ra	inge, may be recoi	rded 11		 	H
				13	3 32		3,
		nument and accessories and/or 839, Lewis Glason s	•		uon t		
1 1 1 1 1	892,Fred A. Ric 894,Fred A. Ric 905, Joseph W. 1 972, Larry Beau 982, D.R. MacNet	, 18 / W. Birch, 8, e, no monumentation e, no monumentation McNeil, found cedar regard, P.S., found 1/1, P.S., found 1/found 1/2" re-rod,	or witness or witness stake, no liron, no v 2" re-rod,	ses given. ses given. witnesses witnesses g no witnesse	iven.	1993, D.R.	•
3. [Description of corner evide	ence found and/or method appli	ed in restoring or r	reestablishing corr	ner:		
Į.	ound 1/2" rebar	raised with 1/2" r	ebar.		, septembri	HHIPPANA.	•
					HARANA E TATE OF	MICHIGAN AND	
		•				RLT.	
					₹0 SUR	SSIONAL OF THE VEYOR	
		F.A. 345 ALI	PENA COUNTY	,		No. 7452	
•		MEER APPROV	ED 9/29/4	71	POFE	SSIONALGUA	
		1/4	B. all			Mitthey.	
). C	Description of monument fo	or corner and accessories estab	olished to perpetua	ate locating the po	sition of the co	rner:	
		priately stamped A			tation Al	uminum Car)
	n existing 1/2" 45° W 59.90' P o	X 24" rebar in mon wer Pole	ument box,	witnessed:			
S	45° W 60.55' Po	wer Pole					
3	40° W 86.80' Te	lephone Riser					
N	45° E 62.69' Fe 70° W 84.22' Fe	nce Corner					
1.4	70 W 54.22 F6	ence Pust					
				Decemb	er 6, 199	4	
	ed by Frank		5				
hane	d by Za Carl	1 - The	Date	,			

27452

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAM., 1983