

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Alpena

(County)

Located In:Corner Code ##

1. Public Land Survey

T 30N R 07E

C5

2. Property Controlling in Section

S T R

3. Miscellaneous Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

JUN 17 10 58 AM '96
Kathy G. M. P. Lash
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Earl T. Lewis, in a field survey on April 10, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
1839: Lewis Glason Set corner. Witnesses given: Spruce 9 S 57° E 9, Cedar 17 N 74° W 34
1888: W. Leroy Established corner. No monumentation given. Witnesses given: White Pine Stump 16 S 61° E 37, Cedar Stump 12 N 43-1/2° W 21.
1914: J. McNeill Set new stake in place of old one. No witnesses given.
1978: D.R. MacNeill, P.S. Used corner. Found 1/2" rerod. Witnesses given: S 45° E 44.82' Fence Post, N 30° E 82.03' 6" Cedar, S 50° W 68.76' 9" Cedar.
1993: Earl T. Lewis, P.S. Used corner. Found 1/2" rod. Witnesses given from notes: N 25° W 56.90' Fence Post, N 45° E 89.90' 8" Poplar, S 45° E 44.60' Fence Post, S 45° W 48.00' Fence Post.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1996: Found 1/2" rerod with unidentifiable cap 3' South of the centerline of Napper Road and on the centerline of Wolf Creek Road.

SURVEY &
REMONUMENTATION

JUL 23 1996

COMMISSION

P.A. 345 ALPENA COUNTY
PEER APPROVED 5/5/96
D. D. B. Lash

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1996: Placed appropriately stamped Alpena County Remonumentation 3" aluminum cap on existing 1/2" rerod, 0.6' below surface.

Witnesses given:
S 45° W 48.34' Fence Post (found nail w/cap #22435)
S 35° E 82.08' 9" Cedar
N 40° E 92.50' 15" Cedar
N 45° W 67.20' 15" Cedar



Signed by Earl T. Lewis Date June 12, 1996
Surveyor's Michigan License No. 27452