

JAN 25 2001

SECTION

2000 Alpena County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alpena

(County)

Located In:

Corner Code #



L- 2 P- 313

08/14/2000 10:20A

Page: 1 of 1

MI LDC 9.00

Kathy J. Matash, Register Alpena Co., MI

1. Public Land Survey

T 30NR 07E

E-9

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Wayne T. Lewis, in a field survey on 2-24-00, ~~19X~~ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1839: Lewis Clason set post and witnessed.

1901: J. W. McNeil found large stake in center of cross roads, no witnesses given.

1907: J. W. McNeil found old stake and set new stake and stone, no witnesses given.

1998: T. L. Fabis, P.S. found pipe w/cap, no witnesses given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe w/cap, damaged, 3' South of Marwede Road C/L and 4' West of King Settlement Road C/L.

This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 ALPENA COUNTY
PEER APPROVED 7-12-2000
N.D.B. L

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2000: Placed 3" Alpena County Remonumentation Cap, stamped to identify the corner, on 1/2" rerod driven inside of existing pipe.

Witnesses:

N 50° E 48.00' Wood Fence Corner (set tag #41922 over large disk w/nail)

S 40° E 39.40' Guy Pole (set tag #41922 over large disk and nail)

S 55° W 41.87' P. Pole (set tag #41922 over large disk and nail)

N 35° W 47.91' Wood Fence Post (set tag #41922)



Signed by Wayne T. Lewis

Date August 14, 2000

Surveyor's Michigan License No. 41922