

SURVEY & REMONUMENTATION
 1994 Alpena County Remonumentation Corner

LIBER

1 PAGE 327

APR 06 1995

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
 ALPENA COUNTY MI

DEC 12 9 30 AM '94

Myra A. Johnston
 REGISTER OF DEEDS

For corners in COMM. SECTION

Alpena
 (County)

Located In:

Corner Code #

1. Public Land Survey	T	30N	R	7E	G-13
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous	S		T	R	
Property in Sec.	S		T	R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

Earl T. Lewis

July 22

94

I, _____, in a field survey on _____, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(GLO) September 1, 1839, Lewis Glason set post, no monumentation given, witnesses given: Fir 8, N 26 W, 13/Tam 8, 53 E, 23
 1896 Fred A Rice, no monumentation or witnesses given.
 1915, Joseph W. McNeil, no monumentation or witnesses given.
 1976, Alpena County Road Commission found 6" concrete monument, place monument box, no monumentation given, witnesses given:
 N 60° W 65.94' Power Pole / N 70° E 61.40' Fence Corner / N 75° E 68.56' Guy Pole
 1982, D.R. MacNeill, found monument box, no witnesses given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found 1/2" rebar in monument box.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: Place Appropriately stamped Alpena County Remonumentation Aluminum Cap on existing 1/2" rebar in monument box, witnessed:

N 45° W 47.30' Power Pole
 N 80° E 106.90' Power Pole
 S 50° E 153.87' 4" Red Pine
 S 40° E 191.92' 4" Red Pine

P.A. 345 ALPENA COUNTY
 PEER APPROVED *9/29/94*

Ed B. Lewis

December 5, 1994

Signed by Earl T. Lewis

Date

Surveyor's Michigan License No. 27452