ANTRIM COUNTY
MICHIGAN
RECEIVED FOR RECORD

DEC 4 2 23 PM '96

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

wande Q. Onway

For corners in	REGISTER OF DEEDS
Located In: Corner Code #	
1. Public Land Survey	
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	2 6 5 4 3 2 1
I, Terry B. Smith in a field survey on Nov. 18, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	3 4 -7 - 8 - 9 - 10 - 11 - 12 - 5 - 6 - 18 - 1716 - 15 - 14 - 13 - 7
recovered, found as expressed below:	8 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
•	11
	12 31 32 33 34 35 36
A Description of original monument and accessories and/or subsequent restoration: GLO Ran North on East side of Sec. 1 to intersection with 4th correction line set post 26.84 east from 4 corner on south side sec 31, T31 Beech 30 S20E 55 Sug 12 S37W 74	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corn	ner:
1885 County Surveyor F. Church survey for James Peckham found stake witnesses gone 1974 Plat of A-Ga-Ming 1979 survey by G. De La Meter found ½" iron at plat distance	
UP S05E 46.00 in acc 10" Maple S40F 34 25 PO 345	ed by Peer Group ordance with
25873 Arthur Nov. 2	L. Lennox 6, 1996 . 3, 1996

Surveyor's Michigan License No.