

1994 Alpena County Remonumentation Corner

DEC 07 1994

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alpena _____
(County)

COMMISSION

Located In:

Corner Code ##

Public Land Survey

T 31N R 7E

K-9

2 Property Controlling
in Section

S _____ T _____ R _____

S T R

3 Miscellaneous

S _____ T _____ R _____

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Daniel T. Kibbe, in a field survey on June 23, 1994,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

[illegible]

A. Description of original monument and accessories and/or subsequent restoration:

1855: G.L.O. Re-survey by Butler Ives - set post & referenced: Y. Pine 20 - S 58 W - 18 /
W. Birch 7 - N 30 E - 8.

1890: Survey by Wm. H. LeRoy - original corner plain

1891: County Survey by Wm. H. LeRoy - Cedar stake 2 1/2" sq. for cor. & referenced.

1961: Monument Witness Record by N.C. Caldwell - Set 1" pipe.

1963: MSHD Construction Plans - referenced 1" pipe.

1968: MSHD - Re-witnessed 1/2" iron rod.

1977, 78, 81, 84, 87: Survey by Duane MacNeill - found mon. box.

13. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found 1/2" iron bar in monument box.

This corner position is compatible with county and local surveys and agrees with MDOT records. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 ALPENA COUNTY
PEER APPROVED Sept. 8, 1994
Dan B. Carter

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: Placed 3" aluminum cap stamped to identify the corner over existion 1/2" iron rod in monument box.

Referenced:

S 60° W - set nail over scar in 16" Norway Pine - 136.63'

N 64° W - fnd. flagged spike in S. side power pole - 174.85'

N 33° E - set nail in 18" Norway Pine - 98.77'

S 24° E - set nail in power pole - 73.00'

Signed by

Surveyor's Michigan License No. 37278

Date August 3, 1994

