

1997 Alpena County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

00002 Page 0099

For corners in

<u>Alpena</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 32N R 05E	<u>K13</u>
	T 31N R 05E	<u>K01</u>
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

STATE OF MICHIGAN
County of Alpena
Recorded
08-25-1997 12:02:00
Kathy J. Matash
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, Wayne T. Lewis, in a field survey on March 3, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1855: Butler Ives, D.S. Set post. Witnesses given: Dead Cedar 12 N 32° W 3, Dead Cedar 8 N 61° E 15.
1888: William Leroy Found old corner. Set 3" square cedar stake in ditch on East side of road. No witnesses given.
1913: J. McNeil & W. Leroy No monumentation or witnesses given.
1976: R.S. Scott Assocs. Found 1/2" rod. Witnesses given: N 45° E 57.82' Power Pole, S 46° E 34.85' 16" Bam, East 99.33' 18" Spruce.
Thomas L. Fabis, P.S. Found 3/4" iron rod. No witnesses given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Found 5/8" rod. Set 1/2" rerod.

P.A. 345 ALPENA COUNTY
PEER APPROVED 5/1/97

[Signature]

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1997: Placed appropriately stamped Alpena County Remonumentation 3" aluminum cap on set 1/2" rerod, 6" below driveway surface.

Witnesses given:
N 85° E 18.58' Gate Post
N 45° E 57.90' Power Pole
S 45° E 35.05' 16" Bam Stump (found nail)
S 43° E 49.35' 6" Aspen



Signed by Wayne T. Lewis
Surveyor's Michigan License No. 41922

Date August 21, 1997