

SURVEY & REMONUMENTATION

NOV 16 1998

1998 Alpena County Remonumentation

SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

00002 Page 0166

For corners in

Alpena

(County)

Located In:

Corner Code #

1. Public Land Survey

T 32NR 06E

T 32NR 05E

T R

T R

T R

T R

T R

T R

A-6

M-6

2. Property Controlling
in Section

S

S

S

S

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

I, Wayne T. Lewis, in a field survey on 5-19, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1857: GLO, Josiah Knauer, D.S. - found old post & witnessed
1890: William H. Leroy, C.S. - found corner; set new stake in place of old one; buried plow point & iron pot; & witnessed
1902: William H. Leroy, C.S. - found stake
1915: Joseph W. McNeil, C.S. - set new stake in place of old one & deposited pieces of iron kettle around same
1976: David B. Guthrie, P.S. - found iron, raised with railroad spike & witnessed
1993: Earl T. Lewis, P.S. - found railroad spike and raised with 1/2" rod & witnessed

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998: Used witness from E.T.L. survey; dug 3-foot-deep hole & got strong pull with metal detector; unable to find corner without digging larger hole; set 1/2" rerod, 3' long, from E.T.L. 1993 witnesses.

E.T.L. 1993 Witnesses:

S 30° E 52.00' Power Pole

N 85° E 31.90' Road Sign

S 30° W 60.23' Guy Pole

S 45° W 67.95' 5" Maple

This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1998: Placed 3" Alpena County cap, stamped to identify the corner, on existing rod, 6" below road surface.

Witnesses:

S 30° E 52.00' Power Pole (found nail)

S 30° W 60.23' Guy Pole

S 45° W 67.75' 6" Maple

S 40° W 64.27' 6" Cottonwood

STATE OF MICHIGAN

County of Alpena

Recorded

10-08-1998 09:57:25

Kathy J. Matash

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

P.A. 345 ALPENA COUNTY

PEER APPROVED

8/10/98

D. D. B. Carter



Signed by

Wayne T. Lewis

Date September 19, 1998

Surveyor's Michigan License No.

41922