

## 1994 Alpena County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alpena  
(County)

Located In:

Corner Code ##

1. Public Land Survey T 32N R 6E E-9 (NW, 28)  
T \_\_\_\_\_ R \_\_\_\_\_ Long Rapids Twp.  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, Thomas L. Fabis, in a field survey on May 25, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

## A. Description of original monument and accessories and/or subsequent restoration:

- 1856: G.L.O. Resurvey by Josiah Knauer - set post & referenced: (Cedar 6 - S64°E - 6 lks., Cedar 10 - N85°W - 20 lks.)
- 1893: County Survey by Wm. H. LeRoy - set plough frame for corner.
- 1916: County Survey by Jos. W. McNeil - drove gas pipe next to corner.
- 1976, 1978 and 1985: Surveys by David B. Guthrie - Found  $\frac{1}{2}$ " iron rod & referenced.
- 1980: Survey by Duane MacNeill - Found  $\frac{1}{2}$ " iron rod & referenced.
- 1992: Survey by Earl T. Lewis - Found  $\frac{1}{2}$ " iron rod & referenced.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1994: Found  $\frac{1}{2}$ " iron rod at intersection of road centerlines. Found old shiner tags in the following witness objects: (5" Cedar - S45°E - 61.1' and P. Pole - N45°W - 83.55'). This corner is compatible with county and local surveys and is accepted as a careful and faithful perpetuation of the position of the original corner.

SURVEY &  
REMONUMENTATION

JUL 30 1994

## SECTION

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1994: Removed existing corner material and set  $\frac{1}{2}$ " iron rod with 3" dia. aluminum cap, stamped to identify the corner, inside a Monument Box.
- Reestablished witnesses are:
- Exis. Shiner in 5" Cedar - S45°E - 61.1'
- Exis. Shiner in P. Pole - N45°W - 83.55'
- Set tag #31591 in 3" R. Pine - S68°W - 53.20'
- Set tag #31591 in 5" R. Pine - N 78°W - 53.38'

P.A. 345 ALPENA COUNTY  
PEER APPROVED Oct. 27, 1994  
Det. B. L. L.

Signed by

Thomas L. Fabis

Date

Dec. 5, 1994

Surveyor's Michigan License No.

31591

