

SURVEY & REMONUMENTATION
APR 06 1995
COMMISSION

LIBER 1 PAGE 325 007151

RECORDED
ALPENA COUNTY MI.

DEC 8 10 11 AM '94

Myriam A. Johnston
REGISTER OF DEEDS

For corners in
Alpena

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|------------|-----------------------------|
| 1. Public Land Survey | T 32N R 6E | E-10 (W $\frac{1}{2}$, 28) |
| | T R | Long Rapids Twp. |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

| | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

Thomas L. Fabis, in a field survey on May 25, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1856: G.L.O. Resurvey by Josiah Knauer - set post & referenced (dead Beech 5 - N41W - 7 lks, Dead Hemlock 7 - S42E - 39 lks).
- 1889 and 1893: County Surveys by Wm. H. LeRoy - Found cedar stake in road.
- 1978 and 1985: Surveys by David B. Guthrie - Set $\frac{1}{2}$ " iron rod 4' East of centerline of Leer Rd. by single proportionate measurement as per county survey records.
- 1992: Survey by Earl T. Lewis - Found $\frac{1}{2}$ " iron rod & referenced.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1994: Found $\frac{1}{2}$ " iron rod 4' East of Centerline of Leer Road and two existing witness objects (S60°W - 68.20 - P. Pole, S45°E - 67.40 - Fe. Post) as per 1992 survey by Earl T. Lewis. This corner position is compatible with county and local surveys and is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1994: Removed existing corner material and set $\frac{1}{2}$ " iron rod with 3" dia. aluminum cap, stamped to identify the corner, inside a Monument Box.
- Reestablished witnesses are:
- Exis. roofing nail in P. Pole - S65°W - 68.20'
 - Exis. roofing nail in Cor. Fe. Post - S40°E - 67.20'
 - Set tag #31591 in Fe. Post - N45°E - 54.81'
 - Set tag #31591 in Apple Clump - N45°W - 50.00'

P.A. 345 ALPENA COUNTY
PEER APPROVED Oct. 27 1994
Det B. Cuth

Signed by *Thomas L. Fabis* Date *Dec. 5, 1994*

Surveyor's Michigan License No. 31591

