

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Alpena

(County)

Located In

Corner Code #

1. Public Land Survey		T	32N	R	6E	K-10
		T		R		
2. Property Controlling In Section	S 25	T	32N	R	6E	8
	S	T		R		
3. Miscellaneous Property in Section	S	T		R		
	S	T		R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on September 15, 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-10 GLO Josiah Knauer D.S. July 1856
Set quarter section post
Wit: 18" Beech N69.5°W 9 Links
8" Beech S88.5°E 23 Links

8- This corner position was not established during the original government survey.

Wm H. LeRoy, September 1891, page 242, county survey notes tied to corner while surveying in the area.

Wm H. LeRoy, May 1935, page 244, county survey notes replaced stake with 4"X4" concrete monument.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-10 Found ½" iron rod in concrete fitting Wm. H. LeRoy's distance north and south.

8- Established the northeast corner of the northwest quarter of the southwest quarter of section 25 per standard BLM instructions for subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-10 ½" iron rod in concrete
Wit: 3" White pine East 28.50'
4" Spruce S46°E 23.23'
8" Spruce S52°W 82.24'
5" Scotch pine N13°W 68.78'
Centerline of N-S road East 1'

8- Set 5/8X32 rerod with cap PS#33981
Wit: 6" Maple S73°W 133.64'
6" White Birch N42°W 57.19'
4" Balsam N03°W 32.19'
3" Balsam N75°E 51.46'
Fence corner Post N72°W 114.05'
Carsonite Post North 1'

Signed by:

Carl T. Kiiskila

Date:

11-23-99

Surveyor's Michigan License No.:

33981

