1993 Alpena County Remonumentation Corner

LIBER

1 PAGE 285

LAND CORNER RECORDATION CERTIFICATE

RECORDED

| | | Filing Require | ALPENA COUNTY MI. | |
|-----|----------------------------|---|----------------------------------|--|
| Fo | r corners in | | | |
| | Al pena | Located In: | Corner Code ## | DEC 16 10 19 AM '93 |
| | (County) | | | DEC 10 10 IS SIN JJ |
| 1. | Public Land Survey | T <u>32N</u> R <u>8E</u> T R | <u>I - 7</u> | REGISTER OF DEEDS |
| | | T R | | WEGIGLER OF BEEDS |
| 2. | Property Controlling | S R | | |
| | in Section | S | | |
| 3. | Miscellaneous | S R | | Register of Deeds Stamp & File Num |
| | Property in Sec. | S R | | |
| 4. | Lot No, | Recorded Plat | | A B C D E F G H I J |
| 5. | Private Claims | | | |
| | | | | |
| | | | | |
| . г | Nuane R. MacNeill | ., in a field survey on | July 23 93 | 7 - 8 - 10 - 11 - 11 - 11 - 11 - 11 - 11 |
| | | equirements of P.A. 74, Michigan P.A. | | ioned |
| | | in conformance with regulations and | • | Q L .19L |
| | | ructions of the United States Depart | | |
| Ma | nagement or by a decree of | f a Court of Law and/or that the corner | r points mentioned in lines 3, 4 | and 5 8 10 20 21 22 22 |

on this certificate. A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

1855 - Cedar Post

Witnesses:

expressed below:

Hemlock 9 N 74° E 12 S 41° W <u> 1901</u> - County Surveyor Leroy set Cedar Stake using old bearing trees.

1938 -County Surveyor McNeil replaced stake with a 6"x 36" Concrete Mon

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 6"x6" concrete monument during Remonumentation field work Corner recorded in 1992 by Tom Fabis #31591

Witnesses:

S 09° E 18.96 24" W. Pine S 65° W 19.13' Power Pole N 16° W 15.57 8" Maple S 86° E 36.26 24" Maple

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Alpena County Remonumentation Aluminum Cap, appropriately stamped, secured to rerod extending from existing monument.

Witnesses:

24" Hemlock Fd. South 18.98 S 78° 19.10' Power Pole Fd. 15.54 N 05° W 6" Maple Fd. S 80° E 36.27

23" Maple Fd.

Witnesses were freshened as necessary; nails replaced with duplex nails bearing a brass washer stamped license #19237

Surveyor's Michigan License No. 19237

December 6, 1993 Date _

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JA REVISED M REVISED