

DEC 10 1993

LURE

1 PAGE 273

007737

COMMISSION

1993 Alpena County Remonumentation Corner

RECORDED
ALPENA COUNTY MI.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

DEC 7 9 20 AM '93

For corners in

Alpena

(County)

Located In:

Corner Code =#

1. Public Land Survey

T 32N R 8E

F/G-5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

Other #

Marilyn A. Johnston
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

I, Daniel T. Kibbe, in a field survey on July 1, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1855: G.L.O. Re-survey by Josiah Knauer - set meander post and referenced:
Balsam 6 - Corner tree / Poplar 15 - N24W - 7 / Cedar 5 - S18E - 6 1/2.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found 2" pipe 0.1' below grade, 15' West of west shore Long Lake. The position of this corner is compatible with the 1855 G.L.O. survey and fits local surveys in Sections 9 and 16. The 2" pipe is the best evidence of the meander corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Set 1/2" x 18" iron rod inside 2" pipe with 3" aluminum cap stamped to identify the corner. Referenced:
S20°W - 8" Ash - 20.50 feet
West - 10" Maple - 22.86 feet
N38°W - 11" Ash - 41.94 feet
S33°E - 18" Willow - 54.82 feet



Signed by

Daniel T. KibbeDate November 24, 1993Surveyor's Michigan License No. 37278