

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

DEC 16 10 19 AM '93

For corners in

Alpena

(County)

Located In:

Corner Code #

1. Public Land Survey

T 32N R 8EI - 6.9

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Sec.

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Manigault A. Johnston
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Duane R. MacNeill, in a field survey on November 24, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1855 - Cedar Post (Meander corner)

Witness:

Cedar 11 S 51° W 43

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument position has been destroyed by reliction of Long Lake.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" x 42" rerod capped with appropriately stamped Alpena County Remonumentation Aluminum Cap, set on line according to G.L.O. evidence and subsequent surveys 192.00' Northerly of Section corner common to Sections 14, 15, 22 and 23. Shore of Long Lake is 21' North of M.C.

Witnesses:

S 60° W 5.03' 8" Cedar
N 18° W 5.11' 10" Cedar
S 50° E 17.44' 6" Cedar
S 02° E 23.29' 6" Hemlock

Signed by

Duane R. MacNeill

Date

December 6, 1993

Surveyor's Michigan License No.

19237

