

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Alpena

(County)

Located In

Corner Code #

1. Public Land Survey

T 32N R 8E J-3
T 32N R 8E K-5

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Section

S T R
S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 19, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3			2		1	
3													
4	7		8		9		10			11		12	
5													
6	18		17		16		15			14		13	
7													
8	19		20		21		22			23		24	
9													
10	30		29		28		27			26		25	
11													
12	31		32		33		34			35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

J-3 GLO Josiah Knauer, D.S. 1855

Set quarter section post

Wit: 30" Hemlock S20°E 10 links

6" Beech N38°W 28 links

K-5 GLO Josiah Knauer, D.S. 1855

Set post corner Sections 11, 12, 13, 14

Wit: 12" Sugar N55°W 25.5 links

12" Beech S 68°E 24 links

Liber 1, Page 224 December 1973 James L. Scott R.L.S.
#8318 ties to corner. No witnesses or type of monument given.

Pages 111 thru 113 County Survey Notes November 1904
Joseph W. McNeil found a large stake standing and both O.B.T.'s down but plain.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

J-3 Found a bent 1/2" rerod fitting James L. Scott's survey in section 11.

K-5 Found a 1/2" rod fitting J.W. McNeil's survey in section 12.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-3 Set standard DNR monument

Wit: *8" White Birch S38°W 19.88'

*8" Maple S80°W 17.22'

*6" Maple S85°W 36.19'

*6" Twin Maple N45°E 44.73'

Carsonite post North 1'

K-5 Found 1/2" rod with cap

Wit: *6" Cedar S75°W 12.03'

*8" Maple N17°W 9.42'

*4" Ironwood S38°E 17.60'

5" Cedar S78°E 27.19'

* Witnesses set by other survey

Signed by:

Carl T. Kiiskila

Date:

12-10-03

Surveyor's Michigan License No.:

33981

