

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Arenac

(County)

Located In

Corner Code #

1. Public Land Survey

T _____ R _____
T _____ R _____

2. Property Controlling
in Section

S 21 T 19N R 3E 6

S 21 T 19N R 3E 2

3. Miscellaneous
Property in Section

S _____ T _____ R _____

S _____ T _____ R _____

4. Lot No: _____

Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on Oct. 13, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - None

2 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

6 - NE 1/16, Sec. 21 -
Set 2" Alum. Cap on 5/8" x 34" rebar per
Standard BLM Procedure.

2 - E 1/16, Cor. common to Sec. 16 & 21 -
Set 2" Alum. Cap on 5/8" x 34" rebar per
Standard BLM procedure.
South 41'± to centerline E-W Gravel Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
S37°W 25.93' to set N & T in SE side 27" Y. Birch
N79°W 56.59' to set N & T in N. side 9" Oak
N39°W 51.18' to set N & T in NE side 8" E. Maple
N57°E 24.35' to set N & T in NW side 21" E. Maple
Set Blue Carsonite Post with loc. tag 1' NW

2 - Set 2" Alum. Cap on 5/8" x 34" iron rebar
N27°E 17.32' to set N & T in NW side 6" Oak
N53°W 27.12' to set N & T in SW side 8" R. Maple
S63°W 22.71' to set N & T in SE side 4" Oak
S56°E 2.13' to set N & T in NE side 6" R. Maple
Set Blue Carsonite Post with loc. tag 1' NW

Signed by:

Craig W. McVean

Date:

11/30/2005

Surveyor's Michigan License No.:

39088