

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Arenac  
(County)

Located In

Corner Code #



201600542

DOC#: 201600542

February 29, 2016 10:46 AM

Fee: \$14.00

Darlene Mikkola  
Register of Deeds  
Arenac County, MI

Page 1 of 1

CD

1. Public Land Survey	T	R		
	T	R		
2. Property Controlling in Section	S 30	T 20N	R 05E	11, 12
	S	T	R	
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on January 14, 2015 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

ARENAC CO. RD. AUGUST 2010

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

**11 – SW 1/16 corner section 30**

**12 – CS 1/16 corner section 30**

1983 – Certificate of Survey, L. 1, p. 491, R Miller  
PS # 16050.

None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**11 – SW 1/16 corner section 30**

**12 – CS 1/16 corner section 30**

Set 2" stamped aluminum cap on 5/8" x 34" rebar per standard BLM procedure. S79°54'W 5.88' to a found 1/2" rebar & cap #16050 not utilized in this survey.

Set 2" stamped aluminum cap on 5/8" x 34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**11 – 2" stamped aluminum cap on 5/8" x 34" rebar.**

**12 – 2" stamped aluminum cap on 5/8" x 34" rebar.**

N70°E 13.90' to set nail & tag in NW side 5" Maple  
S14°E 34.23' to set nail & tag in SE side 25" Oak  
N04°W 6.88' to set nail & tag in E side 4" Maple  
S79°54'W 5.88' to fd. 1/2" rebar & cap #16050  
Set blue post with location tag 1' Northeast

N31°E 37.30' to set nail & tag in SE side 14" Oak  
S88°E 19.31' to set nail & tag in N side 4" Oak  
S05°E 32.78' to set nail & tag in E side 7" White Pine  
S87°W 29.36' to set nail & tag in S side 12" Oak  
Set blue post with location tag 1' Northeast

Signed by:

*Joshua R. Davidson*

Date:

February 24, 2016

Surveyor's Michigan License No.:

46659