## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich., PA 1970

For Corners In: Arenac		Locat	ed In		Corner Cor	ie#						D	OC#	: 20	1600	543	
(County)							Darle	20 ne Mil	016005 kkola	543			ruary 2		6 10:4	3 AM	
1. Public Land Survey		T T	R R			····	Regis Arena	ter of	Deeds inty, M	i I		Fee	: \$14.0	0			
Property Controlling in Section	S 30	T 20N	R	05E	6, 7		Page	1 of	1		CD	J					
Miscellaneous     Property in Section	s s	T	R R R						Pa	aietor			00, R amp &			ag Tag sag	
4. Lot No:	Recorded	i Plat							176.	gistei	UI DE	eus St	amp ox	FIIE IV	umper		
5. Private Claims:								1 A	ВС	D	E F	G H	l J	K	L M		
I, <u>Joshua R. Davidson</u> , in a field survey on <u>October 29</u> , <u>2014</u> do hereby state tha under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Departmen of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, monumented, recovered, found as expressed below:								3	-18		9-16-21-	15	1-	3	12—13—24—24—		
NOTE: Not more than 2 be recorded on this cer		all in the	same	e town a	and range, n	nay		9 10 11 12 13	30	32	28-	27	35	5	25		
A. Description of original	monument	and acce	ssori	es and/o	or subsequer	t restor	ation:										
<u>6</u> – NE 1/16 corner se					·				ner c	omn	non t	o sec	tions	29 8	30		
None  B. Description of corner e	evidence fo	und and/o	ır met	thod app	olied in restor		one e-esta	ablishi	ng coi	rner:		THE LICENSE	1000	OF M OSHU WWW. FERSI FRANCE FR	A R.		
<u>6</u> – NE 1/16 corner section 30						<u>7</u> – N 1/16 corner common to sections 29 & 30											
Set 2" stamped aluminum cap on 5/8" X 34" rebar per standard BLM procedure.						Set 2" stamped aluminum cap on 5/8" X 34" rebar per standard BLM procedure.											
C. Description of monume	ent for corr	er and ac	cesso	ories est	tablished to p	erpetua	ate loc	cating	the po	osition	n of th	e corr	ner:				
<u>6</u> − 2" stamped aluminum cap on 5/8" X 34" rebar.							· 2" stamped aluminum cap on 5/8" rebar.										
N44°E 19.62' to s S37°E 28.29' to s S46°W 70.08' to s N65°W 20.20' to s Set blue post with	et nail & t set nail & set nail &	ag in SW tag in SE tag in NE	. sid . sid . sid	e 13" O e 16" R	ak Pine	S56°E S12°V S88°V N02°V Set bl	N 5.8 N 8.8 N 24.	6' to 0' to .82' to	set na set na o set i	ail & : ail & : nail &	tag ir tag ir k tag	n E. si n S. si in E.	de 8" de 8" side 1	Hem R. M	lock aple	(	
Signed by: Surveyor's Michigan L	L /	1. Z	4665	9		Date		Febr	uary 2	4, 20	16						