

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	BARAGA COUNTY LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>47</u> N. <u>33</u> E. <u>W.</u>		D9, E8
2. PROPERTY CONTROLLING IN SECTION <u>19</u> , T. <u>47</u> N. <u>33</u> E. <u>W.</u>		15
3. MISCELLANEOUS PROPERTY IN SECTION _____ , T. _____ N. _____ E. _____ S. _____ R. _____ W. _____		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on See Below, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner 15: Not set on original survey nor subsequently apparently.

Corner D9: Original monument and accessories not found.

Corner E8: Probable original B.T. 40" White Pine N71½W 31 links. Old Northern Paper Mills notes indicate this to be original BT. Found old Northern Paper Mills location poster.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner 15: Established 3-12-81 on line midway between ¼ corner west and section corner east.

Corner D9: Restored 3-12-81 on line midway between section corners east and west.

Corner E8: Restored 3-16-81 from White Pine stump.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner 15: Set 1" I.D.x32" iron pipe with 4" alum. cap.

10" Balsam N48W 7.1 ft. 1/16S,BT

5" Balsam S59E 4.0 ft. 1/16S,BT

7" Spruce N13E 17.1 ft. 1/16S,BT

Corner D9: Set 1" I.D.x32" Iron Pipe with 4" alum. cap.

6" Tamarack N01W 27.9 ft. ½S,NBT

6" Spruce N67E 26.1 ft. ½S,NBT

4" Tamarack S31E 14.2 ft. ½S,NBT

Corner E8: Set 1" I.D.x36" iron pipe with 4" alum. cap.

6" Balsam S82W 13.9 ft. ½S,NBT

5" Balsam N20E 9.8 ft. ½S,NBT

4" Balsam S22E 12.8 ft. ½S,NBT

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Keith L. Sackett DATE 10-22-81

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Keith L. Sackett

Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

