

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 7 T 47N R 33W	16
	S 6 T 47N R 33W	10
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 16 01/26/2012
10 02/02/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 7) East 1/16 corner between Sections 7 and 18. Not previously monumented.

(10-Sec. 6) South 1/16 corner between Section 6 T47N-R33W and Section 1 T47N-R34W. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 7) Established the position for the corner midway and on the Section line between Section
corner 1322.75' east and Quarter corner 1322.75' west.

(10-Sec. 6) Established the position for the corner midway and on the Range line between Section
corner 1312.18' south and Quarter corner 1312.18' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" Ironwood N34E 2.95' mrkd "1/16S BT"
8" Sugar S18E 18.1' do
9" Sugar S30W 14.75' do
12" Sugar N28W 20.9' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
13" W.Spruce N09E 14.4' mrkd "1/16S BT"
9" Y.Birch N88W 39.2' do
24" Hemlock N51W 35.8' do
5" Maple N30W 10.0' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/26/2012

For the Michigan Department of Natural Resources, Forest Resources Division

