

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: August 16, 2017

For corner(s) in: Baraga County

## Original Public Land Survey Corner

## Corner Code

S          T          R           
S          T          R           
S          T          R           
S          T          R         

## Property Corner

## 1/16 Corner Code

a. S 18 T 48N R 31W 5 (GCDB 140460)  
b. S 18 T 48N R 31W 6 (GCDB 160460)  
S          T          R           
S          T          R         

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A. Corner History

a.) Center-North 1/16 corner, Section 18. Not previously monumented.

b.) Northeast 1/16 corner, Section 18. Not established in the original survey. Found no subsequent record.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found no evidence of prior monumentation. Established the position for the corner midway and on a straight line between Quarter corner 1322.53' north and Center of Section 1322.53' south.

b.) Established the position for the corner at the intersection of 1/16 lines. The North 1/16 line running easterly from 1/16 corner #5 being the weighted mean bearing of: the north line of the Section from B5 to the MC at Lake Ruth; and the E-W 1/4 line from B6 to C6. From the position thus established, I found a 1/2" iron pipe, set by persons unknown, projecting 26" above ground S73°E 19.1' distant, which I did not accept as marking the position for the corner.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Maple in clump N19°W 28.0' mrkd "1/16S BT"  
4" Balsam S65°E 3.75' do  
3" Spruce S25°E 10.7' do  
3" Balsam N79°W 3.8' do  
Set sq'd cedar post adjacent.  
E= 7905610.841 N= 198238.851

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" Balsam N62°E 23.8' mrkd "1/16S BT"  
14" Poplar N75°E 36.35' do  
5" Balsam S48°E 29.5' do  
3" Balsam S25°W 17.4' do  
Set sq'd cedar post adjacent.  
E= 7906013.738 N= 198228.064

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID AA8080: N=192972.689 m. E= 7925456.741 m.

Stephan J. Szyszkoski

09/12/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

