

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numerical data for registration purposes.

I, Stephan J. Szyszkoski, in a field survey on 12 05/29/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 9) Center-South 1/16 corner, Section 9. Not previously monumented.

(13-Sec. 9) Southeast 1/16 corner, Section 9. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 9) Established the position for the corner midway and on a straight line between Quarter corner F5 and the intersection of 1/4 lines of Section 9.

(13-Sec. 9) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" Spruce S46°W 19.8' mrkd "1/16S BT" 5" Spruce N37°W 3.25' do 9" Balsam N66°E 11.3' do 4" twin Spruce S45°E 2.6' do Set sq'd cedar post adjacent. E= 7899236.759 N= 199161.951

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 3" Balsam N15°W 5.2' mrkd "1/16S BT" 3" Balsam N53°E 13.75' do 3" R.Pine S21°W 26.8' do 9" Sugar N44°W 30.4' do Set sq'd cedar post adjacent. E= 7899639.037 N= 199160.564

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum). Coord. Ref.=NGS PID RL1468: N= 199449.721 m. E= 7900600.011 m.

Signed by [Signature] Date 06/18/2014
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division