

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 24 T 48N R 33W	8 (GCDB 620340)
	S 26 T 48N R 33W	4 (GCDB 520260)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 8 08/22/13  
4 09/19/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 24) Center-West 1/16 corner, Section 24. Not previously monumented.

(4-Sec. 26) Northwest 1/16 corner, Section 26. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 24) Established the position for the corner midway and on a straight line between Quarter  
corner 1325.25' west and Center of Section 24 1325.25' east.

(4-Sec. 26) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Balsam N73°E 10.55' mrkd "1/16S BT"  
5" Maple in clump S48°E 21.95' do  
7" Balsam S35°W 8.05' do  
3" Y.Birch S77°W 13.35' do  
Set sq'd cedar post adjacent.  
E= 7894041.053 N= 196457.985

(4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
3" B.Ash N03°E 5.2' mrkd "1/16S BT"  
3" B.Ash N78°E 11.8' do  
8" B.Ash S58°E 4.45' do  
4" Balsam S83°W 9.4' do  
Set sq'd cedar post adjacent.  
E= 7892412.459 N= 195286.807

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL1468: N= 199449.721 m. E= 7900600.011 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 09/03/2014

For the Michigan Department of Natural Resources, Forest Resources Division