

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 48N R 33W	11
	S T R	(GCDB 520620)
	S 2 T 48N R 33W	13
	S T R	(GCDB 560620)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11 12/16/15 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 2) Southwest 1/16 corner, Section 2. Not previously monumented.

(13-Sec. 2) Southeast 1/16 corner, Section 2. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 2) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

(13-Sec. 2) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" Ash S86°E 8.65' mrkd "1/16S BT"  
6" Ash S33°E 18.9' do  
10" Spruce N01°W 13.7' do  
3" Balsam S30°W 4.18' mrkd "X X"  
Set sq'd post adjacent.  
E= 7892523.346 N= 200914.108

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
11" Spruce N67°E 9.3' mrkd "1/16S BT"  
7" Maple S36°E 8.6' do  
5" Y.Birch S85°W 17.05' do  
3" Basswood N26°W 13.85' do  
Set sq'd cedar post adjacent.  
E= 7893328.225 N= 200896.261

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Cogrd. Ref.=NGS PID D08499: N= 221257.626 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski Date 01/05/2016  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division