

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 34W	E2
	T R	
	T R	
2. Property Controlling in Section	S 5 T 48N R 34W	7
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 09/19/12 & 09/24/12 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E2) Quarter corner common to Sections 4 and 5. 1853 - Established by Francis Coleman, Deputy Surveyor, on the Section line between Section corners 40.00 chains south and 39.60 chains north. Set post. Hemlock 10" N51E 16 links, Y.Birch 14" S50W 21 links.

(7-Sec. 5) North 1/16 corner between Sections 4 and 5. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E2) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner on the Section line between Section corners 2623.65' south and 2597.41' north, the position being proportionate to the original record.

(7) Established the position for the corner on the Section line between Quarter corner 1311.82' south and Section corner 1285.58' north, being 20 chains, proportionate to the dimensions given on the official plat, north of the Quarter corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E2) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
9" Maple N46E 28.2' mrkd "1/4S NBT"
6" Maple S17E 4.65' do
4" Maple in clump S54W 18.2' do
9" Poplar N02W 6.5' do
Set sq'd cedar post adjacent.
E= 7879331.068, N= 201547.411

(7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
15" Double R. Pine N06E 33.6' mrkd "1/16S BT"
28" W.Pine N45E 19.7' do
3" B.Spruce S35E 11.7' do
6" B.Spruce S24E 5.35' do
Set sq'd cedar post adjacent.
E= 7879337.184, N= 201947.145

Bearings are magnetic. Coordinates are MCS83 in meters.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/26/2013

For the Michigan Department of Natural Resources, Forest Resources Division

