

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 32 T 48N R 34W	9
	S 32 T 48N R 34W	11
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 04/01/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 32) East 1/16 corner Section 32. Not previously monumented.

(11-Sec. 32) Southwest 1/16 corner Section 32. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 32) Established the position for the corner midway and on a straight line between Center of
Section 1319.84' west and Quarter corner 1319.84' east.

(11-Sec. 32) Established the position for the corner at the intersection of straight lines
connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Tamarack N10°W 23.2' mrkd "1/16S BT"
3" B.Spruce N29°E 22.55' do
3" Tamarack S08°W 2.6' do
4" Tamarack S57°W 5.75' do
Set sq'd cedar post adjacent.
E= 7878764.031 N= 193538.241

(11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" W.Birch N49°W 9.75' mrkd "1/16S BT"
4" Spruce N20°W 14.3' do
3" Balsam N19°E 16.8' do
5" B.Spruce N57°E 29.3' do
Set sq'd cedar post adjacent.
E= 7877947.766 N= 193157.207

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No 33986

Date 07/31/2013

For the Michigan Department of Natural Resources, Forest Resources Division

