

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 28 T 49N R 32W S 28 T 49N R 32W S _____ T _____ R _____	6 5 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 08/15/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 28) Northeast 1/16 corner, Section 28. Not previously monumented.

(5-Sec. 28) North 1/16 corner, Section 28. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 28) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

(5-Sec. 28) Established the position for the corner midway and on a straight line between Quarter corner 1309.19' north and the intersection of 1/4 lines of Sec. 28 1309.19' south. The position for the corner falls on a rock bluff 2.5' above a rock ledge and approx. 14' above the bottom of the bluff.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx34" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Sugar N17°W 21.85' mrkd "1/16S BT"
4" Sugar N78°E 19.85' do
7" Sugar S57°E 12.8' do
5" Balsam N85°W 14.15' do
Set sq'd cedar post adjacent. A 4'x7'x3.5' high
boulder is S30°W 1.0 ft. to N'y face.
E= 7899719.551 N= 204735.451

(5) Set a 2" dia. Alum. cap on a 1"IDx10" long
I.pipe grouted around a 5/8"x8" long rebar which
is grouted into a 3/4" hole drilled into the rock
bluff on which the corner falls.
Set measuring nail with MDNR tag in the side of:
9" Hemlock N62°E 9.85' mrkd "1/16S BT"
5" Cedar S35°E 12.25' do
9" Cedar S50°W 7.85' do
6" Cedar N20°W 5.15' do
E= 7899325.416 N= 204745.228

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)

Coord. Ref.=NGS PID RL0041: N= 210246.990 m. E= 7895426.989 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/04/2013

For the Michigan Department of Natural Resources, Forest Resources Division

