

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Baraga County

Original Public Land Survey Corner

Corner Code

S T R
S T R
S T R
S T R

Property Corner

1/16 Corner Code

a. S 19 T 49N R 32W 7 (GCDB 200360)
a. S 20 T 49N R 32W 3 (GCDB 200360)
b. S 19 T 49N R 32W 9 (GCDB 160340)
S T R

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6		5		4		3		2		1		2	
3													3	
4	7		8		9		10		11		12		4	
5													5	
6	18		17		16		15		14		13		6	
7													7	
8	19	●	20		21		22		23		24		8	
9													9	
10	30		29		28		27		26		25		10	
11													11	
12	31		32		33		34		35		36		12	
13													13	
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) North 1/16 corner between Sections 19 and 20. Not previously monumented.

b.) Center-East 1/16 corner, Section 19. Not previously monumented.



Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Aug 22, 2017. Established the position for the corner midway and on the Section line between Section corner 1315.09' north and Quarter corner 1315.09' south. An attempt was made to monument the corner position with a 1"IDx28" iron pipe with 2" alum. MDNR cap, but subsurface roots and rock prevented the installation of the monument at the exact corner position. Set an 8" long iron spike at the corner position. The top center of the cap of the aforementioned monument, which is wedged tight and firm, is S70W 0.15', the monument leans E'ly about 0.2'.

b.) Aug. 31, 2017. Established the position for the corner midway and on a straight line between Quarter corner 1315.87' east and the Center of Section 19 1315.87' west.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set an 8" long iron spike at the corner with a capped 1"ID iron pipe adjacent. Set measuring nail with MDNR tag in the side of:

9" Maple N40°E 2.35' mrkd "1/16S BT"
7" Hemlock S51°E 30.4' do
7" Hemlock S22°W 9.1' do
5" Maple N51°W 1.15' do

Top Center of cap of 1" pipe S70W 0.15'

Set sq'd cedar post adjacent.

E= 7896995.494 N= 206387.686

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RL0041: N=210246.994 m. E=7895426.985 m.

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:

5" Maple N60°E 17.35' mrkd "1/16S BT"
5" Sugar S64°E 23.25' do
6" Sugar S24°W 21.7' do
6" Sugar N15°W 7.75' do

Sq'd a 6" Balsam Fir, adjacent.

E= 7896584.025 N= 205991.533

Stephan J. Szyszkoski

10/04/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908