

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: July 31, 2017

For corner(s) in: Baraga County

## Original Public Land Survey Corner

## Corner Code

S          T          R           
S          T          R           
S          T          R           
S          T          R         

## Property Corner

## 1/16 Corner Code

a S 20 T 49N R 32W  
S          T          R           
S          T          R           
S          T          R         

6 (GCDB 260360)

|    |   |    |   |    |   |    |   |    |   |    |   |    |   |    |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|----|
| 1  | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M | 1  |
| 2  |   | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   | 2  |
| 3  |   |    |   |    |   |    |   |    |   |    |   |    |   | 3  |
| 4  |   | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   | 4  |
| 5  |   |    |   |    |   |    |   |    |   |    |   |    |   | 5  |
| 6  |   | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   | 6  |
| 7  |   |    |   |    |   |    |   |    |   |    |   |    |   | 7  |
| 8  |   | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   | 8  |
| 9  |   |    |   |    |   |    |   |    |   |    |   |    |   | 9  |
| 10 |   | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   | 10 |
| 11 |   |    |   |    |   |    |   |    |   |    |   |    |   | 11 |
| 12 |   | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   | 12 |
| 13 | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M | 13 |

## Part A. Corner History

Northeast 1/16 corner, Section 20. Not previously monumented.



## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the North and South being monumented. The position for the corner falls in an inaccessible location. Established two WITNESS CORNERS on the east 1/16 line: 200.88' north of the corner position and 86.18' south of the corner position.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

Set 1"IDx28" I.pipe with 2" alum. MDNR cap 200.88' north of the corner position for a WITNESS CORNER. Set measuring nail with MDNR tag in the side of:  
3" B.Spruce N15°E 4.7' mrkd "WC BT"  
4" Maple S81°E 15.7' do  
6" B.Spruce S48°W 4.5' do  
7" B.Spruce N80°W 11.9' do  
E= 7898162.186 N= 206445.454 (the W.C.)

Set 1"IDx28" I.pipe with 2" alum. MDNR cap 86.18' south of the corner position for a WITNESS CORNER. Set measuring nail with MDNR tag in the side of:  
7" Cedar N77°E 11.15' mrkd "WC BT"  
9" Maple S56°E 7.6' do  
8" Cedar S20°E 12.6' do  
5" Maple S49°W 10.25' do  
Set sq'd cedar post adjacent.  
E= 7898161.333 N= 206357.970 (the W.C.)

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL0041: N=210246.994 m. E=7895426.985 m.

Stephan J. Szyszkoski

10/04/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908