

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 29 T 49N R 34W	6
	S 29 T 49N R 34W	12
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10/29/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6) Northeast 1/16 corner, Section 29, also being the NW corner of Gov't Lot 1 and the NE corner of Gov't Lot 2. Not
previously monumented.

(12) South 1/16 corner, Section 29. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6) Established the position for the corner at the intersection of a straight line between 1/16
corners #5 and #7 with a line from 1/16 corner #2 having a bearing which is the mean of the N-S 1/4
line of Sec. 29 and a line between E9 and E10.

(12) Established the position for the corner midway and on a straight line between Quarter corner
1323.36' south and Center of Section 1323.35' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" R.Pine N27°W 14.0' mrkd "1/16S BT"
8" R.Pine N14°E 5.1' do
6" R.Pine S79°E 16.95' do
5" W.Pine S02°W 15.2' do
4"x4" treated wood post adjacent.
E=7879021.269 N=205156.932

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" J.Pine N03°W 19.9' mrkd "1/16S BT"
6" J.Pine S78°E 19.4' do
6" J.Pine S03°W 21.85' do
4" J.Pine N72°W 8.9' do
4"x4" treated wood post adjacent.
E=7878601.862 N=204363.449

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

