

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 20 T 50N R 33W	12
	S 20 T 50N R 33W	1
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 1 07/28/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 20) South 1/16 corner, Section 20. Not established in the original survey.

(1-Sec. 20) West 1/16 corner between Sections 17 and 20. Not established in the original survey.
Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 20) Established the corner midway and on a straight line between Center of Section 20
1319.01' north and Quarter corner 1319.01' south. The corner position is not monumented. To
facilitate forestry work north of the Falls River, I placed a monument on the N-S 1/4 line of Section
20 426.18' north of the corner position for a Witness Corner, and 11' north of the north edge of the
river. The corner position proper is accessible and can be monumented. The Center of Section 20 is
892.83' north.

(1-Sec. 20) Established the corner midway and on the Section line between Section corner 1316.29'
west and Quarter corner 1316.29' east. From the position thus established, the center of Golf Course
Rd. (gravel) is 15' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
stamped "POL Sec. 20 1/4 line", 426.18' north
of the 1/16 corner position for a Witness Corner.
Set measuring nail with MDNR tag in the side of:
9" Maple N41E 19.5' mrkd "POL BT"
24" Cedar S86E 36.1' do
3" Balsam N49W 31.6' do
14" Spruce N35W 41.8' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Maple N28E 34.2' mrkd "1/16S BT"
7" Maple S06W 47.1' do
9" Ash N51W 28.5' do
9" Poplar N10W 17.1' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/24/2011

For the Michigan Department of Natural Resources, Forest Management Division

