

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>50</u> ^{N.} XX , R. <u>34</u> ^{XX} W.	<u>G7 & J7</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____, ^{N.} S. , R. _____, ^{E.} W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____, ^{N.} S. , R. _____, ^{E.} W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

**REGISTER OF DEEDS STAMP AND
FILING NUMBER**

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner G7: Sec. Cor. 15, 16, 21, & 22, T50N, R34W:
Hemlock post (Not found. No subsequent monuments found.)
Hemlock 16 S 9E 17 (" " " " accessories ")
Hemlock 10 N16W 56 (" " " " " ")
Corner J7: 1/4 corner between Sec. 14 & 23, T50N, R34W:
Y. Birch post (Not found. No subsequent monuments found.)
Y. Birch 7 N47W 43 (" " " " accessories ")
Hemlock 12 S86E 21 (" " " " " ")

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner G7: Re-established 9/18/74 proportionately on line between original corners 79.778 ch. S and 39.889 ch. N. My experience in this township, covering some 26 miles of retracements, indicates that the direction of N & S ^{lines} is a more accurate indicator of original corner locations than are E & W distances, which in most cases vary considerably from the original record distances. On that premise, therefore, the corner was set by a single proportion only.
Corner J7: Re-established 5/12/76 on line between Sec. Cor. 39.34 ch. to E and to W. Distance E to stream is 9.25 ch., compared to record of 11.12 ch., but as this section line is 1.98 ch. short of record distance and in rough terrain, distances to called for line

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

objects are not reliable.

Corner G7: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Red Oak 11 N26°W (mag.) 15.3 ft. "S16, NBT"
Red Oak 8 N32°E (mag.) 22.3 ft. "S15, NBT"
Red Maple 10 S62°W (mag.) 2.2 ft. "S21, NBT"
Note: distances are measured horizontally. Also squared & scribed a 5" sugar maple N44°W 1.5 ft.
Corner J7: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Red Maple 7 N60°W (mag.) 4.6 ft. "1/4S, NBT"
Red Maple 5 N36°E (mag.) 7.1 ft. "1/4S, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE October 25, 1976

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

13581

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

