## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)	-	
1. Public Land Survey	TR	
2. Property Controlling in Section	S 2 T 50N R 34W S T R S 11 T 50N R 34W	16 (GCDB 560600)
3. Miscellaneous Property in Sec.	S T R S T R	(GCDB 520540)
4. Lot No. , Red	corded Plat	

Register of Deeds Stamp & File Number

5. Private Claims

16
12/14/15
2

I, Stephan J. Szyszkoski, in a field survey on 8
12/15/15
do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 2) East 1/16 corner between Sections 2 and 11. Not previously monumented.

(8-Sec. 11) Center-West 1/16 corner, Section 11. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 2) Established the position for the corner midway and on the Section line between Section corner 1317.62' east and Quarter corner 1317.62' west.

(8-Sec. 11) Established the position for the corner midway and on a straight line between Quarter corner 1316.03' west and the intersection of 1/4 lines of Section 11 1316.03' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A DAY OF THE PROPERTY OF THE P	
(16) Set 1"IDx28" I.pipe with 2" alt	ım. MDNR cap
Set measuring nail with MDNR tag in	the side of
5" Y.Birch N21°E 38.55' mrkd	"1/16S BT"
14" Hemlock S51°E 36.10'	do
10" Sugar S48°W 12.85'	do
10" Y.Birch N60°W 15.95'	do
Set sq'd cedar post adjacent.	
E= 7884152.991 N= 219854.547	

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Poplar N02°W 6.0' mrkd "1/16S BT"
7" Balsam S64°E 7.0' do
6" Poplar S85°W 1.1' do
5" Poplar N55°W 12.05' do

Set sq'd cedar post adjacent. E= 7883342.415 N= 219063.260

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID D08499: N= 221257.621 m. E= 7884435.168 m.

Signed by Stephen Synghold
Surveyor's Michigan License No. 33986

Date 01/21/2016

For the Michigan Department of Natural Resources, Forest Resources Division