

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 11 T 50N R 34W	15
	S T R	(GCDB 520500)
	S 12 T 50N R 34W	10
	S T R	(GCDB 600520)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 15 12/07/15
10 12/08/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 11) West 1/16 corner between Sections 11 and 14.
Not previously monumented.

(10-Sec. 12) South 1/16 corner between Sections 11 and 12.
Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 11) Established the position for the corner midway and on the Section line between Section
corner 1314.47' west and Quarter corner 1314.47' east.

(10-Sec. 12) Established the position for the corner midway and on the Section line between Section
corner 1325.63' south and the position for the Quarter corner K4, not monumented, 1325.63' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" Maple N78°W 32.1' mrkd "1/16S BT"
9" Maple S79°E 20.85' do
9" Sugar S12°W 18.85' do
7" Maple S53°W 22.3' do
Set sq'd cedar post adjacent.
E= 7883334.910 N= 218261.748

(10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Balsam N40°E 22.45' mrkd "1/16S BT"
6" Balsam S04°E 15.2' do
11" Balsam S40°W 40.6' do
4" Balsam N85°W 40.6' do
Set sq'd cedar post adjacent.
E= 7884540.929 N= 218637.567

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID D08499: N= 221257.621 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski Date 01/21/2016
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

