

LAND CORNER RECORDATION CERTIFICATE
Filling Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 6 T 51N R 30W	8
	S 6 T 51N R 30W	5
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 09/10/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 6) West 1/16 corner, Section 6. Not previously monumented.

(5-Sec. 6) North 1/16 corner, Section 6. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 6) Established the position for the corner on a straight line between Quarter corner
1372.66' west (20.93 ch. GLO) and Center of Section 6 1311.67' east (20.00 ch. GLO), being
proportionate to the dimensions derived from the original plat of this township.

(5-Sec. 6) Established the position for the corner on a straight line between Quarter corner
1233.83' north (18.77 ch. GLO) and Center of Section 6 1314.71' south (20.00 ch. GLO), being
proportionate to the dimensions derived from the original plat of this township.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Cedar N06°E 19.7' mrkd "1/16S BT"
12" Cedar S38°E 16.1' do
8" Cedar S60°W 12.75' do
3" Maple N48°W 14.5' do
Set sq'd cedar post adjacent.
E= 7911074.254 N= 229772.212

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
18" Hemlock N29°E 25.3' mrkd "1/16S BT"
11" Hemlock S58°E 9.9' do
9" Hemlock S17°W 23.2' do
4" Sugar N74°W 11.4' do
Set sq'd cedar post adjacent.
E= 7911479.100 N= 230167.709

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by Stephan J. Szyszkoski Date 10/08/2013
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

