

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 1 T 51N R 31W	16
	S 1 T 51N R 31W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/11/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 1) East 1/16 corner between Sections 1 and 12. Not previously monumented.

(8-Sec. 1) West 1/16 corner, Section 1. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 1) Established the position for the corner midway and on the Section line between Quarter
corner 1328.44' west and Section corner 1328.44' east.

(8-Sec. 1) Established the position for the corner on a straight line between Quarter corner
1325.49' west and the Center of Section 1 1325.49' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" W.Spruce N23°E 13.5' mrkd "1/16S BT"
4" Y.Birch S49°E 5.5' do
10" Cedar S67°W 36.7' do
9" Cedar N68°W 11.2' do
Set sq'd cedar post adjacent.
E= 7910239.401 N= 228981.310

(8) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N46°E 25.3' mrkd "1/16S BT"
13" Hemlock S81°E 49.0' do
4" Sugar S14°W 9.75' do
15" Cedar N75°W 27.0' do
Set sq'd cedar post adjacent.
E= 7909442.732 N= 229795.787

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID D08499; N= 221257.624 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/15/2013

For the Michigan Department of Natural Resources, Forest Resources Division

