

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 5 T 52N R 33W S _____ T _____ R _____ S 5 T 52N R 33W	10 (GCDB 200620) 11 (GCDB 220620)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat	_____	_____
5. Private Claims	_____	_____

I, Stephan J. Szyszkoski, in a field survey on 05/10/16 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 5) South 1/16 corner between Sections 5 and 6. Not previously monumented.

(11-Sec. 5) Southwest 1/16 corner, Section 5. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 5) Established the position for the corner midway and on the Section line between Section corner 1316.34' south and Quarter corner 1316.34' north.

(11-Sec. 5) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the east and west being monumented.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Maple N63°E 41.15' mrkd "1/16S BT"  
6" Maple S16°E 8.15' do  
5" Maple in clump S22°W 8.45' do  
6" Maple N34°W 10.05' do  
Set sq'd cedar post adjacent.  
E= 7883447.999 N= 239485.706

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
20" Hemlock N62°E 26.45' mrkd "1/16S BT"  
5" Sugar S26°E 3.4' do  
13" Hemlock S18°W 22.7' do  
7" Sugar N63°W 19.2' do  
Set sq'd cedar post adjacent.  
E= 7883850.004 N= 239478.526

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL1540: N= 235001.700 m. E= 7887187.199 m.

Signed by Stephan J. Szyszkoski Date 05/17/2016  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

