

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. Recorded Plat
5. Private Claims

I, Stephan J. Szyszkoski, in a field survey on 03/22/16 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 21) Southwest 1/16 corner, Section 21. In 1907 W.W.Stockley, Engineer, partially subdivided Section 21 and blazed the west and south 1/16 lines in the SW1/4 of this section but I found no record of this corner having been established in that survey.
(16-Sec. 16) East 1/16 corner between Sections 16 and 21. In 1907 W.W.Stockley, Engineer, partially subdivided Section 21 but I found no record of this corner having been established in that survey.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 21) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the north and south being monumented.
(16-Sec. 16) Established the position for the corner midway and on the Section line between Section corner 1333.12' east and Quarter corner 1333.12' west. From the position thus established, a cedar fence corner post with unmaintained barbed wire fencing running E-W-S, all down on the ground, bears N45°W 4.0' distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 9" Sugar N03°E 16.4' mrkd "1/16S BT"
(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar S56°E 7.65' mrkd "1/16S BT"
5" twin Sugar S32°W 12.35'
6" Sugar S85°W 11.3'
4" Sugar N25°W 19.2'
Set sq'd cedar post adjacent.
E= 7885399.521 N= 234625.614
E= 7886232.583 N= 235818.757

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL1540: N= 235001.700 m. E= 7887187.199 m.

Signed by [Signature] Date 03/30/2016
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division