

SURVEY &  
REMONUMENTATION

FEB 23 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga

(County)

Located In:

Corner Code #

1. Public Land Survey

T 52N R 33W

#61 North MC for

T      R     

the northernmost

T      R     

crossing of the

T      R     

Sturgeon River

2. Property Controlling  
in Section

S     

T      R     

between A-11 and

S     

T      R     

A-12

3. Miscellaneous

S     

T      R     

Property in Sec.

S     

T      R     

RECEIVED FOR RECORD THIS 31ST  
DAY OF DECEMBER A.D. 1997 AT  
10:30 A.M. AND RECORDED IN  
LIBER 4 OF LAND CORNER  
RECORDATION RECORDS ON PAGE  
821

*Nelda Bishop*

BARAGA COUNTY REGISTER OF DEEDS  
Register of Deeds Stamp & File Number

4. Lot No.           , Recorded Plat             
5. Private Claims           

I, Michael Mileski, in a field survey on 5 December, 19 97 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of  
survey instructions of the United States Department of the Interior, Bureau of Land Management or by a  
decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in  
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;  
established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #6; North Meander Corner for the northernmost crossing of  
the Sturgeon River between A-11 and A-12, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt,  
D.S. in 1845 and monumented by a 14" cedar. No accessories were noted.

No subsequent record evidence bearing upon the location of this corner was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #6; North Meander Corner for the northernmost crossing of the Sturgeon River between  
A-11 and A-12, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the W 1/4  
corner of section 31 and the NW corner of section 31. This corner position falls approximately 26 feet  
north of the left (north) bank of the Sturgeon River.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #6; North Meander Corner for the northernmost crossing of the Sturgeon River between  
A-11 and A-12, T52N, R33W;

Set a 1"(I.D.) x 36" galvanized iron pipe with cap stamped as to location  
flush with the ground.

Set 7" spike	E/side	11" Elm	N11°E	74.23'
Set 7" spike	E/side	6" White Ash	N34°E	82.13'
Set 7" spike	SW/side	7" Sugar Maple	N69°W	92.21'
Set 7" spike	NE/side	11" Elm	N37°W	95.18'
		6' Steel fence post w/ yellow sign	South	1.5'

All of the above new bearing trees are marked with upper and lower blazes.  
The lower blaze is scribed "NBT". Both blazes and a band around the tree  
at the upper blaze were painted red.



LIBER 4 PAGE 821

Signed by *Michael Mileski*  
Surveyor's Michigan License No. 39091

Date 23 Dec 1997