

SURVEY & REMONUMENTATION

FEB 23 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Baraga Located In: Corner Code #
(County)

1. Public Land Survey T 52N R 33W #10 North MC
T R between A-2 and
T R A-3
T R
2. Property Controlling S T
in Section S T
3. Miscellaneous S T
Property in Sec. S T

RECEIVED FOR RECORD THIS 31
DAY OF DECEMBER A.D. 1997 AT
10:30 A.M. AND RECORDED IN
LIBER 4 OF LAND CORNER
RECORDATION RECORDS ON PAGE
825

Relda Bishop
BARAGA COUNTY REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Michael Mileski, in a field survey on 18 November, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #10; North Meander Corner between A-2 and A-3, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Sugar 12 S73°E 18 lks.

No subsequent record evidence bearing upon the location of this corner was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #10; North Meander Corner between A-2 and A-3, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the SW corner of section 31 and the W $\frac{1}{4}$ corner of section 31. This corner position falls in the Sturgeon River approximately 20 feet south of the left (north) bank of the river. A witness corner was established on the section line at a distance of 53.31 feet northerly of the proportioned meander corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #10; North Meander Corner between A-2 and A-3, T52N, R33W;

The witness corner described in Part B was monumented with a 1"(I.D.) x 36" galvanized iron pipe with cap stamped as to location flush with the ground.

Set 7" spike	E/side	10" Sugar Maple	N07°E	36.26'
Set 7" spike	S/side	15" Sugar Maple	N69°E	46.77'
Set 7" spike	SW/side	11" Sugar Maple	N51°W	16.75'
Set 7" spike	E/side	9" Sugar Maple	N18°W	70.56'
		6' Steel fence post w/ yellow sign	East	1.5'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.



LIBER 4 PAGE 825

Signed by *Michael Mileski*
Surveyor's Michigan License No. 39091

Date 23 Dec 1997