

SURVEY & REMONUMENTATION

FEB 23 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Baraga
(County)

Located In: Corner Code #

1. Public Land Survey T 52N R 33W #12) East MC
T R between B-1 and
T R C-1
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

RECEIVED FOR RECORD THIS 31ST
DAY OF DECEMBER A.D. 1997 AT
10:30 A.M. AND RECORDED IN
LIBER 4 OF LAND CORNER
RECORDATION RECORDS ON PAGE
827

Relda Bishop
BARAGA COUNTY REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Michael Mileski, in a field survey on 6 December, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #12; East Meander Corner between B-1 and C-1, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Sugar 9 N30°E 18 lks.

No subsequent record evidence bearing upon the location of this corner was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #12; East Meander Corner between B-1 and C-1, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the N 1/4 corner of section 6 and the NE corner of section 6. This corner position falls in the Sturgeon River approximately 10 feet west of the right (east) bank of the river. A witness corner was established on the section line at a distance of 51.52 feet easterly of the proportioned meander corner. This witness corner is located approximately 40 feet east of the east bank of the Sturgeon River as presently located.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #12; East Meander Corner between B-1 and C-1, T52N, R33W;

The witness corner described in Part B was monumented with a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location set flush with the ground.

Set 7" spike	W/side	16" Red Maple	N23°E	51.21'
Set 7" spike	SE/side	17" Green Ash	N63°E	24.81'
Set 7" spike	N/side	16" Sugar Maple	S57°E	57.08'
Set 7" spike	E/side	8" Balsam	N09°W	21.47'
	6' Steel fence post w/ yellow sign	West		1.5'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

LIBER 4 PAGE 827



Signed by *Michael Mileski*
Surveyor's Michigan License No. 39091

Date 23 Dec 1997