

# LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga  
(County)

Located In:

Corner Code #

RECEIVED FOR RECORD THIS 14TH DAY OF  
JANUARY A. D. 1999 AT 10:30 A. M. AND  
RECORDED IN LIBER 5 OF LAND CORNER  
RECORDATION RECORDS ON PAGE 38.

1. Public Land Survey

T 52N R 33W

#14) East MC for  
the westernmost  
crossing of the  
Sturgeon River  
between A-11 and  
B-11

2. Property Controlling  
in Section

S      T      R       
S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R       
S      T      R     

*Nelda Bishop*  
BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No.           , Recorded Plat             
5. Private Claims           

I, Michael Mileski, in a field survey on November, 19 98 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of  
survey instructions of the United States Department of the Interior, Bureau of Land Management or by a  
decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in  
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;  
established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #14; East Meander Corner for the westernmost crossing of  
the Sturgeon River between A-11 and B-11, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt,  
D.S. in 1849 and monumented with a sugar maple post witnessed by a  
Yellow Birch 10 N76°E 27 lks. and a Fir 6 S22°E 37 lks.  
This corner is not indicated in the field notes of a survey of the north line of  
section 31 conducted by persons unknown for Andrew and Joseph Lescelius  
on 5 September 1933.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #14; East Meander Corner for the westernmost crossing of the Sturgeon River between  
A-11 and B-11, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the  
NW corner of section 31 and the N¼ corner of section 31. This corner position falls in the Sturgeon River.  
A witness corner was established on the section line a distance of 78.00 feet easterly of the proportionate  
meander corner. This witness corner is located 19 feet east of the water's edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #14; East Meander Corner for the westernmost crossing of the Sturgeon River between  
A-11 and B-11, T52N, R33W;

The witness corner described in Part B was monumented with a 1" (I.D.) x 36" galvanized iron pipe  
with cap stamped as to location set 4" below the ground.

Set 7" spike	E/side	5" Butternut	S02°E	46.84'
Set 7" spike	E/side	10" Black Ash	N17°W	73.30'
		7' Steel fence post w/ yellow sign	West	2.0'

The black ash was not marked. The butternut was marked with upper and lower  
blazes. The lower blaze was scribed "NBT". Both blazes and a band around  
the tree at the upper blaze were painted red.

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Baraga County



Signed by Michael Mileski  
Surveyor's Michigan License No. 39091

Date 28 Dec 1998