LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in RECEIVED FOR RECORD THIS 14TH DAY O <u>Baraga</u> Located In: Corner Code # JANUARY A. D. 1999 AT 10:30 A. M. Al (County) RECORDED IN LIBER 5 OF LAND CORNER RECORDATION RECORDS ON PAGE 34. 1. Public Land Survey T 52N R 33W #181/West MC R between B-9 and R COUNTY REGISTER OF DEEDS 2. Property Controlling Т in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat 5. Private Claims Michael Mileski , in a field survey on November , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: MC #18; West Meander Corner between B-9 and C-9, T52N, R33W; Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with an elm post witnessed by an Elm 10 S11°W 24 lks. No subsequent record evidence was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: MC #18; West Meander Corner between B-9 and C-9, T52N, R33W; This corner was considered lost and reestablished on line at the proportionate distance between the N¼ corner of section 30 and the NE corner of section 30. This corner position falls 10 feet west of the water's edge of the Sturgeon River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: MC #18; West Meander Corner between B-9 and C-9, T52N, R33W; Set a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location projecting 8" above ground. Set 7" spike 10" Balsam SW/side S33°E 47.81 Set 7" spike 22" Sugar Maple N/side S58°W 62.94' Set 7" spike 15" Sugar Maple SW/side N57°W 101.231 6' Steel fence post w/ yellow sign East 2.0' All of the above new bearing trees were marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red. MICHAEL MILESKI APPROVED LAND CORN

Surveyor's Michigan License No._ <u> 39091</u> ROFESSIONA SURVEYOR

P.A. 345 OF 196 Baraga County