

SURVEY &
REMONUMENTATION

FEB 17 1998



2643

Page: 1 of 1
12/16/1997 12:15P

Sandy Schondelmayer - Barry Co. LCRCR

SECTION

BARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in
BARRY COUNTY

Located In:

Corners Code #

1. Public Land Survey
1/4 COR COMMON
TO SEC'S. 12& 13
BARRY TWP.

T..1N R..9W
T..... R.....
T..... R.....
T..... R.....

....L-5....

2. Property Controlling
in Section

S.....T..... R.....
S.....T..... R.....

3. Miscellaneous
Property in Sec.

S.....T..... R.....
S.....T..... R.....

4. Lot No....., Recorded Plat.....

5. Private Claims.....

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, RAYMOND MOORED, in a field survey on JANUARY 20, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. S. SIBLEY, D.S. 1826; WEST CORRECTED 39.92 SET POST; W. OAK 36 N561/2W 19; B. CHERRY 6 S89E 24 LCRC # 436 BY ROBERT CARR, RECORDED 23 JULY 91; FD. SLEIGH RUNNER WITH BRICK; 30" OAK S30W 35.84'; 40" OAK N50E 39.14'; 14" CHERRY S60E 48.06'; 12" WALNUT N75W 60.07'; 10" WALNUT N45W 10.36'; 6' +/- NORTH OF C/L ROAD.

ACT 132 SURVEY BY R. CARR 23 JULY 91 LIB.2, PG. 34-35; SAME WITS AS ABOVE.

ACT 132 SURVEY BY R. MOORED 9 APRIL, 1996 LIB. 2, PGS 128-130.

NO OTHER HISTORICAL EVIDENCE AVAILABLE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND SLEIGH RUNNER AND BRICK PER LCRC # 436 ABOVE. WITNESSES CHECKED. SET BARRY COUNTY REMONUMENTATION IRON W/ CAP AND ACCEPTED THIS POSITION AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED BY BARRY COUNTY REMON PEER GROUP ON 11 March, 96 BR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD BARRY COUNTY REMONUMENTATION IRON WITH CAP

NAIL IN SW SIDE 10" WALNUT NNW 63.00'

NAIL IN SE SIDE 40" OAK N50E 38.55'

NAIL IN SW SIDE 12" WALNUT N45W 9.80'

NAIL IN N SIDE 14" CHERRY S60E 48.22'

C/L ROAD SOUTH 6' +/-

Signed by Raymond Moored
Surveyor's Michigan License No. 26463

Date 12/11/97

