

DEC 9 2 10 PM '96

Sandy Schindelmayer
REGISTER OF DEEDSBARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

BARRY COUNTY
(County)

Located In:

Corner Code #

- | | | 1N | 10W | H-5 |
|-------------------------|---|----|-----|-----|
| 1. Public Land Survey | T | R | | |
| | T | R | | |
| SEC COR COMMON TO | T | R | | |
| SEC'S 10 & 15 | T | R | | |
| 2. Property Controlling | S | T | R | |
| in Section | S | T | R | |
| 3. Miscellaneous | S | T | R | |
| Property in Sec. | S | T | R | |

002446

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, RAYMOND E. MOORED, in a field survey on Feb 18, 1995 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4			3		2		1	
3													
4	7		8		9			10		11		12	
5													
6	18		17		16			15		14		13	
7													
8	19		20		21			22		23		24	
9													
10	30		29		28			27		26		25	
11													
12	31		32		33			34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O: SYLVESTER SIBLEY, D.S., 1826 (R10W, P. 24) WEST CORRECTED 40.00 SET POST ON TRUE LINE A.W. OAK 18 N46E 27, DO. 16N1E. 12

JOHN CRESSY OCT. - NOV. 1884 (L.2, P. 252 RESURVEY) FOUND OLD CORNER CEDAR POST & STONE. PUT IN TILE SUGAR 12 N9W 45 1/2 HICKORY 10 S 11 1/2 W 78.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DUG FOR STONE & TILE BUT COULDN'T LOCATE. FD REMAINS OF MAPLE STUMP TO NORTH BELIEVED TO BE CRESSY'S WITNESS TREE. SET STANDARD BARRY COUNTY REMONUMENTATION IRON AT DOUBLE THE DISTANCE FROM SOUTHWEST CORNER AND N-S 1/8 LINE FENCE IN SOUTH WEST 1/4, HOLDING CRESSY'S DISTANCE FROM MAPLE STUMP. ACCEPTED AS BEST AVAILABLE EVIDENCE OF CORNER LOCATION.

ACT 345 BARRY COUNTY REMONUMENTATION
APPROVED BY PEER REVIEW AT A MEETING HELD ON

9 OCT. '95 BR
BRIAN REYNOLDS COUNTY SURVEYOR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD BARRY COUNTY REMONUMENTATION IRON W/CAP.
-PK & TAG NE SIDE 28" MAPLE S60E 42.90'
-PK & TAG SW SIDE 20" CHERRY S40E 29.61'
-PK & TAG E SIDE 12" MAPLE S30W 26.97'
-PK & TAG NE SIDE 20" MAPLE N40W 40.01'
-CENTERLINE ROAD 1.5 SOUTH.
-1/2 IRON W/CAP (26463) NORTH 33.00'

SURVEY &
REMONUMENTATION

MAY 20 1997

COMMISSION

Date 10/7/96



Signed by Raymond E. Moored
Surveyor's Michigan License No. 26463