SURVEY & REMONUMENTATION

BARRY COUNTY REMONUMENTATION

FEB 0 \$ 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION For Corners in BARRY (county)	Located in:	Corner Code #		
1. Public Land Survey CORNER COMMON TO SECTIONS 29, 30, 31 & 32 BALTIMORE TOWNSHIP	T_2N_R_8W TR TR TR		P	2744 lage: 1 of 1 2/17/1998 12:35P
2. Property Controlling S in Section S	T R T R	Sandy Schondelmayer	Register of Deeds Sta	mp & File Number
3. Miscellaneous S	T R		ABCDEF	GHIJKLM
	lat		2 6 5 4 3 4 7 8 9	3 - 2 - 1 -
I, Brian Reynolds, in a field survey on of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules instructions of the United States Depara decree of a Court of Law and/or that were in conformance with the rules of of a Court of Law; established, re-estates expressed below. NOTE: Not more than 2 corners, all in the conformance with the rules of the court of Law; established, re-estates expressed below.	corner points mentioned s therefore as required is tment of the Interior, But the corner points mention the Michigan Board of La blished, monumented, re	I in lines 1 and 2 above were in the current manual of survey breau of Land Management or by coned in lines 3, 4, and 5 above and Surveyors or by a Decree e-monumented, recovered, found	5	-15 14 13
 ALSO: NO NAME (1926 D) \$20°W 53.35' TO 12" SO! ALSO: NO NAME OR DA' PRIVATE NOTES: OF DO! TWIN 6" MAPLE \$45W 49 	: MUSGROVE EVA) NAME OR DATE,)OWLING ROAD P FT MAPLE NO TE (WITNESS CAF N DAVIS, PROVIDI 3.4' 8' 3 & CARR Inc. PRO	NNS, D.S., 1826 (R8W, P.79) (BANFIELD ROAD PLANS) LANS #420, P.3) "STONE" 5°E 49.1' TO 30" MAPLE RD) "STONE ?" P. POLE N ED BY CRANE LAND SURV " MAPLE N65W 61.3' OVIDED BY CRANE LAND S	#597, P. 11) "SEC. COR \$45°W 36.8' TO 18" TR \$20°E 42.0' TO 24" E I3°W 25.5' T. POLE N EYING, MAY, 1983 "5/8" POWER POLE N10W 2 SURVEYING, 30 APRIL, 1	PNT. OF ENDING" IPLE ELM LLM 45°W 47.5' 'IRON" 23.6'
B. Description of corner evidence of FOUND NO MAGNETIC EVID INSTALLATION OF UNDERGOUNDER POWER POLE AND OAK (FOU-11 AS RECITED IN SURVEY HAVE DESTROYED ANY EVID ACCEPTED RESTORED CORSET STANDARD BARRY COL	ENCE OF CORNER ROUND UTILITY C UND NAIL IN POW Y BY KING & CARI DENCE OF STONE NER AS BEST AV	R MONUMENTATION. IRON CABLES. RESTORED CORN VER POLE, NO NAIL IN OAK R (ITEM #6 ABOVE). UNDE E AS RECITED BY ROAD CO VAILABLE EVIDENCE OF CO	WAS APPARENTLY RE IER FROM WITNESSES I I). CONFIRMED POSITIC RGROUND UTILITY INST DMMISSION. DRNER POSITION.	BY CARR AND DAVIS, ON WITH DISTANCE TO FALLATION WOULD
C. Description of monument for co SET STANDARD BARRY COU SET 20d NAIL W/PLASTIC TA SET 20d NAIL W/PLASTIC TA SET 20d NAIL W/PLASTIC TA SET 20d NAIL W/PLASTIC TA FOUND NAIL W/METAL TAG CORNER LIES ROUGHLY ON CORNER LIES 16'+/- NORTH CORNER IS IN LINE WITH FE	JNTY REMONUME AG IN THE NORTH AG IN THE SOUTH AG IN THE NORTH AG IN THE SOUTH IN THE EAST SIDI I CENTERLINE EX OF TRAVELED GI	ENTATION MONUMENT (3/4' WEST SIDE OF A 10" TWIN WEST SIDE OF A 24" MAPL WEST SIDE OF A 16" MAPL EAST SIDE OF AN 8" MAPL E OF A UTILITY POLE N5°W TENDED FROM THE WEST RAVEL CENTERLINE	" X 36" IRON) WITH ALU ASH S77°W 82.29' .E N71°W 55.32' .E S67°W 49.88' .E S42°W 41.18'	BRIAN REYNOLDS LAND SURVEYOR
	APPROVED BY PEER	COUNTY REMONUMENTATION REVIEW AT A MEETING HELD ON		NO 31602
	BRIAN REYNOLDS	COUNTY SURVEYOP		The same of the sa
Signed by Surveyor's Michigan License M	lo 31602	Date	DEC 15, 1998 PPROVED BY MICHIGAN STATE BOARD	OF LAND SURVEYORS, JAN. 28, 1971
Surveyor's Michigan License No 31602 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JANUARY, 1983 REVISED OCTOBER 1995				