APR 08 1996

MENNEY &

CACLEMIES

BARRY COUNTY REMONUMENTATION

AND COOKED DECORDATION OFFITTERS

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

Nec 15 13 no PM 195

COMMISSION	Filing Requirement of Act 74, Mich. P.A. 1970			Sandry Schondelmaryer					
For corners in									
(County)	Located in:	Corner Code ##	·	REGISTER OF DEEDS					
1. Public Land Survey SECTION CORNER COMMON T SECTIONS 11, 12, 13, & 14 HOPE TOWNSHIP	T 2N R9W T R R	K-5	·	00	236	3			
in Section S 3. Miscellaneous S	T R T R T R T R T R T R T R T R T R T R		Register o	of Deeds	Stamp	o & File	e Numb	er	
4. Lot No, Recorder 5. Private Claims	d Plat		A	B C D	E F	G H	J	K L I	
BRIAN REYNOLDS, in a field of hereby certify that under requirement in lines 1 and 2 above were in conform	ts of P.A. 74, Michigan P.A nance with regulations a	A. of 1970, the corner points mention and rules therefore as required in	ned 6	7 8-	9-	10-15-	-11- 	12	
current manual of survey instructions o Management or by a decree of a Court of above were in conformance with the rule Court of Law; established, re-establi expressed below:	Law and/or that the corr es of the Michigan Board	ner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	d 5 8 of a 9	19 20	21-	22-27-	23-	24-25-	
NOTE: Not more than 4 corners,	all in the same town a	and range, may be recorded	11	++	+		1 -		

A. Description of original monument and accessories and/or subsequent restoration:

GENERAL LAND OFFICE: SYLVESTER SIBLEY, D.S., 1826(R9W,P.66)

A W. OAK 11 N14W 30 A BEECH 12 S6E 11

COUNTY SURVEYOR RECORDS: LEE COBB, AUG. 11, 1893(L.2,P.282) "FOUND ONE U. S. TREE"

ELM 12 N9E 1.55 BEECH 12 S6E 11

ALSO: HEATH, OCT. 13-19, 1903(L.3,P.90) "DROVE 2" MILL PIPE, U. S. WITNESS"

"NEW WITNESS ELM 12 N9E 1.55 (CHAINS)"

COUNTY ROAD COMMISSION: CEDAR CREEK ROAD #601, PG.4 "P.I. STA. 33+92.6 IS 6.6' W

AND 344.7' S OF SECTION COR."

on this certificate.

NO OTHER RECORDED HISTORICAL INFORMATION AVAILABLE FOR THIS CORNER.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 2" MILL PIPE SURROUNDED BY BITS OF GLASS, 18+" BELOW GRADE. MEASURED DISTANCES TO J-5 AND K-6 ARE CONSISTENT WITH COUNTY SURVEYOR'S RECORDS.

ACCEPTED FOUND MILL PIPE AS PERPETUATION OF CORNER POSITION BY HEATH.

LEFT MILL PIPE IN PLACE, RAISED WITH STANDARD REMON IRON AND CAP

ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

13 March '95

BRIAN REYNOLDS

COUNTY SURVEYOR



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT (3/4"X36"W/ALUMINUM CAP)

SET 40d NAIL W/PLASTIC TAG IN THE NORTHWEST SIDE OF AN 18" MAPLE S67°W 20.66'

SET 40d NAIL W/PLASTIC TAG IN THE NORTH ROOT OF A 14" MAPLE S47°W 18.52' SET 40d NAIL W/PLASTIC TAG IN THE WEST ROOT OF A 20" MAPLE S12°E15.23'

SET 40d NAIL W/PLASTIC TAG IN THE WEST TRUNK 12" MAPLE CLUSTER S5°W 25.94'

SET 40d NAIL W/PLASTIC TAG IN THE WEST SIDE OF A 16" MAPLE S40°E 12.70"

6'+/- NORTH OF AN EAST-WEST WOVEN WIRE FENCE

APPROXIMATELY ON EXTENDED CENTERLINE OF ABANDONED ROAD BED EXTENDED NORTH

	; ; ;	
Signed by Su	9 - -	Date 12/15/95
Surveyor's Michigan License No. 3/602	•	CORM ADDROVED BY MICHICAN STATE BRADE DS (AND SIRVEYDES AND 98 197)