REMONUMENTATION

OCT 2 5 1993

## COMMISSION

## BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COUNTY OF BARRY RECEIVED FOR RECONT

3 33 PH 193

Sandy Schondelmaryer	
REGISTER OF DEEDS	

For corners in Barry	• · · · · · · · · · · · · · · · · · · ·	Corner Code ##	Sandy Schondelmaryes
(County)	Located In: YANKEE SPRINGS		REGISTER OF DEEDS
1. Public Land Survey	T 3N R 10N T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R R T R R T R R R T R R R T R R R T R R R T R R R T R R R T R R R T R R T R R R T R R R T R R R T R R R T R R R T R R R T R	<u>K4</u>	002087
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, F 5. Private Claims	Recorded Plat		2 6 5 4 3 2 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4
do hereby certify that under re in lines 1 and 2 above were in current manual of survey instruments Management or by a decree of above were in conformance we	, in a field survey onApri quirements of P.A. 74, Michigan P.A n conformance with regulations a ructions of the United States Depa a Court of Law and/or that the corn ith the rules of the Michigan Board re-established, monumented, re-	a. of 1970, the corner points mention and rules therefore as required in the interior, Bureau of the points mentioned in lines 3, 4, of Land Surveyors or by a Decre	oned n the Land and 5 8 19 20 21 22 23 24 29 28 27 26 25
NOTE: Not more than 4 con this certificate	corners, all in the same town a	and range, may be recorded	11 32 33 34 35 36-

A. Description of original monument and accessories and/or subsequent restoration:


K4: Post established by U.S. Deputy Surveyor S. Sibley in 1831 - accessories: W. Oak 8 S42W 29 links & W. Oak 8 N31W 110 links. No other records found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K4: Reestablished corner at the intersection of an East - West fenceline and a 33' offset line from the treeline running North along the East R.O.W. of Yankee Springs Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K4: Set 1/2" rebar with plastic cap stamped "G.C. Bilow LLS 26453" in Monument box in centerline road Rast 32.19', Nail & Tag in 29' Oak N26E 71.43', Nail & Tag in 32' Oak M85W 48.13', Hail & Tag in 19" Oak \$47W 63.11', Nail & Tag in 7" Oak



Signed by Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983

10/26/93