

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>31</u>	T. <u>4</u> N. S. R. <u>9</u> E. W.	A-11, A-12
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER \_\_\_\_\_

I, Gary C. Bilow, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on March 25, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

<p>A-11 No record since GLO</p>	<p>A-12 County Surveyor Mershon W. Oak 12, S21°E, 46.21 W. Oak 18, N79-1/2°W, 74.58</p>
-------------------------------------	-----------------------------------------------------------------------------------------------------

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

<p>A-11 Found pointed stone with stones around in N-S fence line at tree row East, 17.2 feet North of NE corner section 36, T4N, R10W.</p>	<p>A-12 Found 1-1/4" well point 3.14 feet NNW of 3/4" iron recorded as corner in Record No. 49</p>
------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p>A-11 Replaced stone with 1/2"x36" rebar encased in a 4" concrete cylinder with an aluminum cap (DNR monument). N 1° W, 13.17 feet, nail &amp; tag in 24" Oak N79°E, 10.65 feet, nail &amp; tag in 12" Oak S11°E, 32.86 feet, nail &amp; tag in 14" Oak S2°W, 17.2 feet, DNR monument @ NE corner Section 36</p>	<p>A-12 Accepted well point for northing of corner. Set DNR monument on line between E 1/4 and NE corner Sec. 36 at well point northing. S 0°E, 2.80 feet, 3/4" rod-E 1/4 cor. Sec. 36 S77°E, 46.32 feet, nail &amp; bottlecap in 20"W.Oak S78°W, 78.02 feet, nail &amp; bottlecap in 36"W.Oak N 1°E, 28.32 feet, nail and bottlecap in pp</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 26453 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)