

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Benzie</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>26N</u> R <u>13W</u>	<u>H8</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u>22</u> T <u>26N</u> R <u>13W</u>	<u>9</u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

4. Lot No. , Recorded Plat

5. Private Claims

I, Craig W. McVean, in a field survey on Aug. 7 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H8 - Rec. Survey L.2
P. 466 - Calc. C 1/4 - B.J. Jenema - 1994

9 - None.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H8 - C1/4, Sec. 22 - Set 2" A.C. on 5/8" x 34" Rebar per Standard BLM Procedure. Fits Rec. Survey Dimensions.

9 - CE 1/16, Sec. 22 - Set 2" A.C. on 5/8" x 34" Rebar per Standard BLM Procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H8 - 2" A.C. on 5/8" x 34" Rebar with Carsonite Post 1' SW.
N50°E 1.85' to N&T in W. Side 12" R. Oak
S52°E 32.46' to N&T in NE Side 16" R. Oak
S25°W 24.35' to N&T in SE Side 12" R. Oak
S70°W 15.00' to N&T in N. Side Tw. 15" R. Oak

9 - 2" A.C. on 5/8" x 34" Rebar with Carsonite Post 1'SW and set 4"
Cedar Post 1' E.
N32°W 9.82' to N&T in E. Side 9" S. Maple
West 8.96' to N&T in Face 48" W. Pine STP.
N72°E 44.50' to N&T in N. Side 8" S. Maple
S10°E 33.21' to N&T in E. Side 3" W. Pine

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



Signed by Craig W. McVean
Surveyor's Michigan License No. 39088

Date 3/29/2000